13.2% Transmire 17.1

APPENDIX A

Energy Systems Group Rockwell International 8900 DeSoto Avenue Canoga Park, California 91304

Docket No. 70-25 License No. SNM-21

Notice of Violation

Based on the results of the NRC inspection conducted on January 22-24, 1979, it appears that certain of your activites were not in full compliance with applicable NRC regulations and conditions of your license as indicated below.

a. 10 CFR 73.50 (c)(1) states in part, "At the point of personnel access into a protected area, all individuals shall be searched for devices such as firearms, explosives, and incendiary devices, or other items which could be used for industrial sabotage."

Contrary to the above, the inspector observed on January 22-24, 1979, that armed security officers were not searched when entering the protected area.

This is an infraction and a repeated item of noncompliance.

b. 10 CFR 73.60 (b) states in part, "Each individual, package, and vehicle shall be searched for concealed special nuclear material before exiting from a material access area..."

Contrary to the above, the inspector observed on January 24, 1979, two protective services personnel ent ~ the fuel fabrication, a material access area, and exit the protected area through Gate #5 without the mandatory search for special nuclear material.

This is a deficiency and a repeated item of noncompliance.

STATE OF THE STATE OF

Copy II of II copies

THE LOCALINET IS NOT TO BE

REPROPULED WITHOUT SPECIMS

APPROVAL OF ILLY