## NRC FORM 591 PART 1

(7-91)

10 CFR 2.201

## SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

			Page 1 of
	ston Edison Company D Boylston St Wa ston, Massachusetts	it-Lab	INAL OFFICE  REGION I  U S NUCLEAR REGULATORY COMMISSION  475 ALLENDALE ROAD  KING OF PRUSSIA PA 19406-1415
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
030-17486		20-07626-03 our	December 2, 1993
Regulatory Cor	mmission (NRC) rules and reg	gulations and the conditions of your li-	as they relate to radiation safety and to compliance with the Nuclear cense. The inspection consisted of selective examinations of as by the inspector. The findings as a result of this inspection are as
X 1. Withi	n the scope of this inspection	, no violations were observed.	
	inspector also verified the step tions on those actions at this t		ions identified during the last inspection. We have no further
		our activities, as described below or at equired to be posted in accordance v	ttached, were in violation of NRC requirements. This form is a with 10 CFR 19.11.
A.			was not properly posted to
F			. 10 CFR 20.203(b),(c),(d),(e) or 34.42.
В.			of sealed sources were not
	performed at the proper free	quencies. 10 CFR	or License Condition Number
c.	Records of		were not properly maintained.
	10 CFR	or License Condition Number	
D.	Documents were not proper	ly posted or otherwise made available	. 10 CFR 19.11.
E.	Reports or notification of		were not made in accordance with
	10 CFR	or License Condition Number	
F.	9. P. C	402040016 931221 DR ADOCK 03017486 PDR	
	DESIGNATED OF Gentified by: 2	RIGINAL	

I hereby state that, within 20 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NAC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

030006

RETURN CRIGINAL TO REGION I

IE:07