

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

March 26, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



02 MAR 30 11:02

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/82010

The enclosed report provides details concerning Surveillance
Instruction 4.1.B.2 (average power range monitor output signal
calibration) which was not performed within the required frequency.
This report is submitted in accordance with Browns Ferry unit 2
Technical Specification 6.7.2.b(3).

Because of an incorrect statement in our previous licensee event
report (260/82010) we are resubmitting the report to you.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Coffey
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

OFFICIAL COPY

8205040660 820326
PDR ADOCK 05000260
S PDR

An Equal Opportunity Employer

TE 22
5/1