



EDISON DRIVE  
AUGUSTA, MAINE 04336  
(207) 623-3521

July 2, 1982  
MN-82-128

JHG-82-123

United States Regulatory Commission  
Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation  
Division of Licensing  
Operating Reactors Branch #3  
Mr. Robert A. Clark, Chief

Reference: (a) License No. DPR-36 (Docket No. 50-309)  
(b) USNRC Letter to MYAPCo dated February 23, 1982  
(c) MYAPCo Letter to USNRC dated April 28, 1982 - MN-82-86

Subject: TMI-II.B.1 - RCS Vent System - Operating Guidelines

Dear Sir:

In Reference (c) we committed to providing operating guidelines for the RCS Vent System. These guidelines are enclosed. Please note that the guidelines were developed for both emergency operating procedure development and support of management decisions in Technical Support Center. Maine Yankee has not included in the Emergency Operations Procedure all of the contingencies addressed in the guidelines.

We trust this information is satisfactory. However, should you have any questions, please contact us.

Sincerely yours,

MAINE YANKEE ATOMIC POWER COMPANY

A handwritten signature in cursive script that reads "John H. Garrity".

John H. Garrity, Senior Director  
Nuclear Engineering and Licensing

A046

JHG:pjp

Enclosure - TMI-II.B.1 Guidelines - 17 pages

8207130385 820702  
PDR ADOCK 05000309  
F PDR