

# Duquesne Light Company

Beaver Valley Power Station  
P.O. Box 4  
Shippingport, PA 15077-0004

February 1, 1994

JOHN D. SIEBER  
Senior Vice President and  
Chief Nuclear Officer  
Nuclear Power Division

(412) 393-5255  
Fax (412) 643-8069

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

**Subject:** Beaver Valley Power Station, Unit No. 1 and No. 2  
BV-1 Docket No. 50-334, License No. DPR-66  
BV-2 Docket No. 50-412, License No. NPF-73  
Disposition of Error Notices Received From  
Boeing Computer Services

**Reference:** Letter from Leif J. Norrholm, Chief, Vendor  
Inspection Branch to Duquesne Light Company  
dated December 16, 1993

Duquesne Light Company (DLC) has reviewed the error notices from Boeing Computer Services which were enumerated in the referenced letter. DLC has determined that all of the subject notices were previously dispositioned in accordance with a station procedure to address computer code error notices. This procedure has been in place since 1986 when we first began using computer codes from Boeing Computer Services.

The types of errors reported fall into four major categories: informational notices, errors reported on code modules not used, errors reported on commands not used, and errors with potential consequences. The errors reported in each of these areas have no significance relative to safety since they have not affected the results of any analysis which used the codes GTSTRUDL, NUPIPE II, and ANSYS from Boeing Computer Services.

Should you have any questions regarding this response, please contact John Maracek at (412) 393-5232.

Sincerely,

*John D. Sieber*  
J. D. Sieber

cc: Mr. L. W. Rossbach, Sr. Resident Inspector  
Mr. T. T. Martin, NRC Region I Administrator  
Mr. G. E. Edison, Project Manager  
Mr. Leif J. Norrholm, Chief, Vendor Inspection Branch

9402090260 940201  
PDR DDOCK 05000334  
PDR



4001  
1/0