


C-E Power Systems
Combustion Engineering, Inc.
1000 Prospect Hill Road
Windsor, Connecticut 06095

Tel. 203/688-1911
Telex. 99297



May 6, 1982

Mr. U. Potapovs, Chief
Vendor Programs Branch
United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Reference: Docket 99900401/82-01
Letter from U. Potapovs to
M. R. Etheridge, received
26 April 1982

Dear Mr. Potapovs:

C-E Power Systems Group's response to the referenced letter of April 20, 1982 is as follows:

NONCONFORMANCES:

Contrary to Section 17.5 of CENPD-210-A; Section 2.2 of Quality Assurance of Design Procedure (QADP) 5.3 (Interface Control) Revision 1, dated May 1, 1980; and Section 6.4.2 of Plant Engineering QA Procedures (PEQAP) 001 (Design Quality Assurance Procedure) Revision 0, dated October 1, 1974; the following specifications did not have the required documentary evidence of interface reviews on file:

Project Specification No. 6473-PE-231, Revision 5, dated January 12, 1981, (QADP 5.3); General Specification No. 00000-PE-707, Revision 2, dated February 19, 1975, (PEQAP 001).

Response

Specification 6473-PE-231, Revision 5, will be rerouted with a Document Distribution/Approval (DD/A) form to reconstruct the missing form. This will be completed by May 31, 1982. Specification 00000-PE-707, Revision 2, was superseded by Revision 3. An unsigned DD/A form, with a note indicating that the original DD/A form was lost, will be attached to the Specification record copy. This will be completed by May 31, 1982.

8207130457 820702
PDR GA999 EMVC-E
99900401 PDR

Mr. U. Potapovs, Chief
Vendor Programs Branch

-2-

May 6, 1982


Memo (PCE-82-031) was issued to all PCE (Plant Components section of the Plant Engineering Dept.) personnel March 30, 1982 describing the requirements, clarifying the procedure, and directing additional study of procedure QADP 5.3 - Interface Control. This will be completed and documented on training records by April 30, 1982.

This constitutes the corrective preventive action relative to this nonconformance.

If you have any questions relative to this response, please contact me.

Very truly yours,

COMBUSTION ENGINEERING, INC.



M. R. Etheridge
Vice President
Power Systems Group

MRE/PDF/ss