

APPENDIX A
NOTICE OF VIOLATION

Department of the Army
Walson Army Hospital

Jocket No. 30-02501

Fort Dix, New Jersey 08640

License No. 29-07513-01

As a result of the inspection conducted on May 14, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. 10 CFR 20.207(a) requires that licensed materials stored in an unrestricted area be secured against unauthorized removal from the place of storage. 10 CFR 20.207(b) requires that materials not in storage be under constant surveillance and immediate control of the licensee. As defined in 10 CFR 20.3(17), an unrestricted area is any area access to which is not controlled by the licensee for purposes of protection of individuals from exposure to radiation and radioactive materials.

Contrary to the above, on May 14, 1982, the Nuclear Medicine Laboratory, which contains millicurie quantities of licensed material, was unlocked and not under constant surveillance and immediate control.

This is a Severity Level IV violation. (Supplement IV)

- B. 10 CFR 35.14(e) requires that sealed calibration or reference sources possessed pursuant to 10 CFR 35.14(d) be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, as of May 14, 1982, leak tests have not been performed on the 244 microcurie barium-133 source since June 1980, an interval of more than six months.

This is a Severity Level IV violation. (Supplement VI)

- C. Condition 15 of License Number 29-07513-01 requires that licensed material be used in accordance with statements, representations and procedures contained in an application dated March 25, 1977 and a letter dated September 30, 1977.

The Walson Army Hospital Routine Safety Procedures included with this application, in item 5.k, require that all work with radioactive materials be performed utilizing remote handling tools.

Contrary to the above, on May 14, 1982, Nuclear Medicine personnel handled radioactive material without the use of remote handling tools.

This is a Severity Level IV violation. (Supplement VI)

