

Appendix

NOTICE OF VIOLATION

Control Data Corporation

License No. 22-16718-02

As a result of the inspection conducted on August 11, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:


License Condition No. 17 requires that your chromatograph detector containing nickel-63 be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, as of the day of the inspection, you had not tested your detector containing nickel-63 for contamination or leakage since March 1979, an interval of more than six months.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

8-27-82  
Dated

  
D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1