

ENCLOSURE

NOTICE OF VIOLATION

Honeywell, Inc.
Atlanta, GA

Docket No. 99990002
License No. General License
10 CFR 31.6

During an NRC inspection conducted on January 27, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

10 CFR 31.6 grants, to any person who holds a specific license issued by an Agreement State authorizing the holder to install or service a device described in 10 CFR 31.5 within such Agreement State, a general license to install and service such device in any non-Agreement State, provided that the device has been installed and serviced in accordance with applicable provisions of the specific license issued by the Agreement State.

Honeywell, Inc., holds a specific license (No. GA-832-1G) issued by the State of Georgia (an Agreement State) which authorizes Honeywell to install and service specified generally-licensed devices within the Agreement State.

Condition 13 to Georgia Radioactive Materials License No. GA-832-1G (Amendment 24) requires, in part, that all licensed activities, including servicing, be performed by three named individuals.

Contrary to the above, on September 4, 1991, service was performed on a generally licensed device of a type described in 10 CFR 31.5 in Pennsylvania, a non-Agreement State, and such servicing was not in accordance with the Agreement State license in that the servicing was performed by an individual who was not named on the Agreement State license.

This is a Severity Level IV violation (Supplement VI).

Dated at Atlanta, Georgia
This 3rd day of February 1994

9402150216 940203
PDR GA999 EMVHONE
99990002 PDR