398 DLRICGW 40-943

AUG 2 4 1960

Wah Chang Corporation Albany, Oregon

Attention: Mr. Stephen Yih

Gentleman:

This refers to the inspection conducted on June 14, 1960, of your activities authorized under AEC Bource Material License No. C-4589.

It appears that certain of your activities were not conducted in full compliance with the requirements of the AEC's "Standards for Protection Against Redistion," Part 20, Title 10, Code of Federal Regulations, in that:

- The storage shed which contained approximately 2639 pounds of thorium oxide was not posted as required by Section 20.203(e)(2), "Caution signs, labels and signals."
- The 30 gallon and 3 gallon thorium storage containers within the storage shed were not isbeled as required by Section 20.203(f)(2), "Caution signs, isbels and signals."

These deficiencies were brought to your attention by the inspector and you stated that the storage shed and individual containers would be properly posted and isbaled. Should you have any questions about these matters, please feel free to write us. Posting and labeling will be reviewed during the next inspection of your facilities.

Your cooperation with us is appreciated.

Very truly yours,

cc: Division of Compliance, Hdqtrs. Inspection Division, HDD Public Document Room

Lyell Johnson, Chie	22
Licensing Branch	
Division of Licens	Ing:
and Regulation	

9402150266 930426 PDR FOIA	and Regulation		B/19
OFFICE > 10 CFR 20 Sign: "Caution -	Radioactive Materials"	DLR:RSB COWSITE:LRR	DLR: LB
SLIRNAME .		8-20-60	spr '

Form AEC-318 (Rev. 2-53)

U. S. GOVERBALIT PRINTING OFFICE 16- 62761-3