(7-91) 10 CFR 2.201	SAFETY	INSPECTION	
			Page 1 of
1. LICENSEE Computerized Medical Important Tip W. Hamilton Ave. Ste. B Eau Claire, WI 54701	iging	2. REGIONAL OFFICE REGION III U S NUCLEAR RI 799 ROOSEVELT GLEN ELLYN IL	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S) 5. DATE	OF INSPECTION
030-28773	48-24533-01	Dece	mber 3, 1993
LICENSEE: The inspection was an examination of the all Regulatory Commission (NRC) rules and reprocedures and representative records, interfollows:	gulations and the condition	is of your license. The inspection co	nsisted of selective examinations of
Within the scope of this inspection	, no violations were observ	ved.	
The inspector also verified the ster questions on those actions at this		of the violations identified during the	last inspection. We have no further
3. During this inspection certain of you NOTICE OF VIOLATION, which is			of NRC requirements. This form is a
Α			was not properly posted to
indicate the presence of a			. 10 CFR 20.203(b),(c),(d),(e) or 34.42.
B			of sealed sources were not
performed at the proper free	quencies 10 CFR	or License Condition	Number
C. Records of			were not properly maintained.
10 CFR	CFR or License Condition Number		10001
D. Documents were not proper	ly posted or otherwise man	de available. 10 CFR 19.11.	PUBLIC
E. Reports or notification of _			were not made in accordance with
10 CFR	10 CFR or License Condition Number		
X F 10 CFR 35.50(c)	10 CFR 35.50(c) - licensee failed to test geometry dependence of dose		
calibrator (CRC-	IOR) following re	epair of unit	
9402160065 931203 PDR ADOCK 0302877 C PDR			
I hereby state that, within 30 days, the action above. This statement of corrective actions unless required by the NRC.			
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC INSPECTOR	DATE / /
Now HAWRED	11-12-94	16.1017	1/2/3/93