



*Bon Secours Hospital, 70 East Street, Methuen, Massachusetts 01844*

TEL. AREA CODE 617-687-0151

July 6, 1982

Thomas T. Martin, Director  
Division of Engineering and Technical Programs  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Martin:

This letter is in response to your letter of 24 June 1982, Docket No. 30-13728, License No. 20-13916-02, Inspection Nos. 30-00247/82-01 and 30-13728/82-01.

(1) An evaluation has been made of the radiation dose to the hands and fingers of the individual who injected doses during December, 1981 and January 1982, whose assigned TLD dosimeter was lost. Based on the analysis of the patient load and the technologist's duties during these two months, the estimated doses are: Dec., 1981 -- 150 mrem; Jan., 1982 -- 310 mrem.

(2) The Chief Nuclear Medicine Technologist has been instructed to notify the RSO of any lost, missing or damaged badges to enable the RSO to evaluate and document the required data for occupational exposure records.

(3) Date of compliance was July 6, 1982.

Sincerely,

William L. Lane  
Director

WLL/a11