

APPENDIX A

NOTICE OF VIOLATION

Massachusetts Institute of Technology  
Cambridge Massachusetts

Docket No. 70-938  
License No. SNM-986

As a result of the inspection conducted on June 17-18, 1982 and in accordance with the Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register Notice (47 FR 9987) dated March 9, 1982, the following violation was identified.

Condition 8 of License No. SNM-986 incorporates your application dated May 18, 1966 which requires, in part, that packages, when removed from storage in the BTF Vault will contain SNM in an amount less than or equal to the amount contained in the array of storage trays and the 12 inch edge-to-edge separation of these packages will be maintained at all times.

Contrary to the above, on June 17, 1982 several packages containing SNM in an amount less than or equal to the amount contained in the array of storage trays were located on the floor of the BTF Vault and the 12 inch edge-to-edge separation from each package and the storage array was not maintained.

This is a Severity Level V violation (Supplement VI.E).

Pursuant to the provisions of 10 CFR 2.201, Massachusetts Institute of Technology is hereby required to submit to this office within thirty days of the date of this notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

JUL 13 1982

Dated \_\_\_\_\_

Original Signed By: *R. Keimig for*

\_\_\_\_\_  
R. W. Starostecki, Director  
Division of Project and  
Resident Programs

OFFICIAL RECORD COPY