

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 76A

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

August 25, 1982

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N.W.
Atlanta, GA 30303


Subject: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12 —
Computer Analyzed Gap Requirements
For Guide Restraints -
Significant Deficiency

Dear Mr. O'Reilly:

On July 26, 1982, Mr. John Rogge of the Region II office was informed of a significant deficiency under the provisions of 10CFR50.55(e). This deficiency involved the clearance requirements between safety related piping and their supports when the supports are box type guides. At this time, we have not completed our evaluation on this deficiency. We expect to complete our review and issue a final report in approximately two weeks.

If you require additional information, please advise.

Very truly yours,



O. W. Dixon, Jr.

GM:OWD:tdh

cc: V. C. Summer	A. R. Koon
T. C. Nichols, Jr.	H. Radin
G. H. Fischer	Site Q. A.
O. W. Dixon, Jr.	C. L. Ligon (NSRC)
H. N. Cyrus	G. J. Braddick
H. T. Babb	J. L. Skolds
D. A. Nauman	J. B. Knotts, Jr.
M. B. Whitaker, Jr.	B. A. Bursey
W. A. Williams, Jr.	I&E (Washington)
O. S. Bradham	Document Management Branch
R. B. Clary	*(55e, 21, LER only)
M. N. Browne	NPCF
	File

8209020176 820825
PDR ADOCK 05000395
S PDR

OFFICIAL COPY
IE 27