

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 REGION II
1750 Chestnut Street Tower II

August 26, 1982

2 AUG 30 4 5: 18

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/82024

The enclosed report provides details concerning nonconservatively calculated
reactor thermal power because of an erroneous feedwater flow signal. This
report is submitted in accordance with Browns Ferry unit 2 Technical
Specification 6.7.2.b(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8209020197 820826
PDR ADOCK 05000260
S PDR

OFFICIAL COPY

TE 22