NRC FORM 591 Part 1 (7-91)

(7,91) 10 CFR 2.201

SAFETY INSPECTION

				Page 1 of 2	
1. LICENSEE Syncor International Corp. 1 Syncor Drive Huntington, WV 25705		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323			
3. DOCKET NUMBER(\$)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION		
30-33160	47-25248-01MD		12/10/93		
LICENSEE: The inspection was an examination of the acti Regulatory Commission (NRC) rules and regulatory procedures and representative records, intervisionlows:	lations and the condition	s of your license. The ins	spection consisted of selective exa	amons of	
Within the scope of this inspection,	no violations were observ	ed (see page	2 2)		
The inspector also verified the steps questions on those actions at this tire.		of the violations identified	during the last inspection. We ha	ave no further	
During this in paction certain of you NOTICE OF VIOLATION, which is reconstructed.				This form is a	
A	William Control of the Control of th		was not properly po	osted to	
indicate the presence of a			. 10 CFR 20.203(b),	(c),(d),(e) or 34.42.	
В.			of sealed sources w	vere not	
performed at the proper frequencies. 10 CFR or License Condition Number					
C. Records of were not properly mail rained.					
10 CFR	10 CFR or License Condition Number				
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.					
haman and					
E. Reports or notification of were not made in accordance with					
10 CFR or License Condition Number					
F.					
hanspeconserval					
there is an all and a subject to the property of the subject to th					
9402230034 931210 PDR ADDCK 030331 C PD	60				
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the made in accordance with	Inspector will be taken to h the requirements of 10	correct the violations identified in CFR 2.201. No further response w	the items checked vill be submitted	
SIGNATURE - LICENSEE	DATE	SIGNATURE - NRC INS	PECTOR	DATE	
220050		1 A		12/10/93	

SAFETY INSPECTION

10 CFR 2.201

			rage z oi
1. LICENSEE SYNCOY International Corp. 1 Syncor Drive Huntington, WV 25705		2. REGIONAL O	PFICE REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323
3. DOCKET NUMBER(\$)	4. LICENSE NUMBER(Š)		5. DATE OF INSPECTION
30-33160	47-25248-01MD		12/10/93
3. (Continued)		4	
[] G.			
PERMITTER THE THE PERMITTER AND THE PERMITTER AN			
н			
· Land			
The violations listed below ar remaining criteria in 10 CFR			millied, and corrective action was or is being taken, and the
			d by 10 CFR 21.6 (a).
X A tailore to p	051 accuments	> require	a by 10 crx 2116 (a).
В.			
beautiful Mr. manufacture and			
J			
Min office to the			