



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

FEB - 3 1994

License Nos.: SNM-00031 (Terminated)
Docket Nos.: 70-00038

SMB-00563 (Terminated)
40-02813

SNM-00119 (Terminated)
70-00138

04-00647-03 (Terminated)

Aero Turbine
Attn: David E. Clayton, President
3355 Fostoria Way
San Ramon, California 94583

Aerojet
Attn: Jose Uranga, Senior Counsel
P.O. Box 1322
Sacramento, California 95813

Gentlemen:

SUBJECT: SPECIAL RADIOLOGICAL SURVEY OF THE FORMER AEROJET FACILITIES IN
SAN RAMON, CALIFORNIA

This letter refers to the special inspection and radiological survey conducted by Mr. H. Dean Chaney of this office and Mr. Jeff Wong of the State of California, Department of Health Services, on September 3, 1993, of the facilities formally occupied by Aerojet-General Nucleonics (also known as Aerojet-General Corporation Nuclear Division), a subsidiary of Aerojet General Corporation, part of The General Tire company, located at 3300 Crow Canyon Road in San Ramon, California. Messrs. Chaney and Wong discussed the survey findings with Messrs. Doug Clayton, Mike Nelson, and David Clayton of ONB Associates and Aero Turbine following the inspection.

The enclosed inspection report identifies the areas examined during the inspection. The inspection consisted of a selective examination of historical records, on site observations, limited independent radiological measurements, and interviews with former and current building tenants. Based on the results of this inspection/survey, several areas with fixed low level residual radioactive contamination were identified in Building 1. Building 1 was occupied by the Aero Turbine Company at the time of the surveys. No other contamination was found above current release limits outside of Building 1 or in the other facilities surveyed.

9402230049 940203
PDR ADOCK 07000138
C PDR


JE07/1

No violations of NRC requirements were identified. The residual radioactivity found was determined to be above current NRC release criteria.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning the inspection, we will be glad to discuss them with you.

Sincerely,



James H. Reese, Chief
Facilities Radiological Protection Branch

Enclosure:

Inspection Report Nos. 70-00038/93-01; 40-02813/93-01;
70-00138/93-01; 04-00647-03/93-01

cc w/enclosure:

State of California Department of Health Services,
Radiologic Health Branch

Hugo G. Simens, PE
111 Deerwood Place
San Ramon, CA 94583

San Ramon Valley Unified School District Service Center
Attn: J. Morrison, Director
of Service Operations
3280 E. Crow Canyon Road
San Ramon, California 94583

Trident Corporation
Attn: Todd Mentor
480 Market Place
San Ramon, California 94583

ONB Associates
Attn: Mike Nelson
3355 Fostoria Way
San Ramon, California 94583

bcc w/enclosures:

Docket File

G. Cook

Paul Goldberg, IMOB/NMSS

K. Perkins

J. Horner

D. Kunihiro

W. Axelson, RIII

R. Scarano

F. Wenslawski

C. Hehl, RI

J. Stohr, RII

L. Bell, NMSS/LLDR

S. Collins, RIV

Region V/ann

DChaney *ws*

2/3/94

JReese

2/3/94

REQUEST COPY]
 YES / NO]

REQUEST COPY]
 YES / NO]

SEND TO DCS]
 YES / NO]

SEND TO PDR]
 YES / NO]

220079

FE07