



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

2 AUG 30 4 5 18

NORRIS L. STAMPLEY
SENIOR VICE PRESIDENT

August 25, 1982

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Open Penetrations - Fire Seal
and Secondary Containment
Reference: LER 82-027/03 L-0
AECM-82/361

On July 27, 1982, during a special inspection, it was determined that a fire rated seal was not installed in a spare HVAC penetration to the containment exhaust filter train room and that an open penetration existed in the secondary containment. Attached is LER 82-027/03 L-0.

Yours truly,

NLS:ac
Attachment

cc: Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8209020288 820825
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

TE 22