NRC FORM 591 Part 1 (7-91)

(7-91)

10 CFR 2.201

## SAFETY INSPECTION

Page 1 of /

1. LICENSEE Columbia Regional 404 Keene Stre Columbia MO 65		U S N 799 F	ON III JUCLEAR REGULATORY COMMISSION IOOSEVELT ROAD I ELLYN IL 60137
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	2/-01	5. DATE OF INSPECTION  DECEMBER 20, 1993
Regulatory Commission (NRC) rules and regu	lations and the condition	is of your license. The in	to radiation safety and to compliance with the Nuclear spection consisted of selective examinations of ector. The findings as a result of this inspection are as
questions on those actions at this tir	you have taken to correct ne. r activities, as described	of the violations identified below or attached, were	d during the last inspection. We have no further in violation of NRC requirements. This form is a 9.11.
Aindicate the presence of a			was not properly posted to  10 CFF 20.203(b),(c),(d),(e) or 34.42.  of sealed sources were not  e Condition Number
C. Records of	or License Condition No posted or otherwise man	Numberde available. 10 CFR 19	were not properly maintained.
PA02230174 931220 PDR ADOCK 030107 PI  I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the	Inspector will be taken to	correct the violations identified in the items checked CFR 2.201. No further response will be submitted
SIGNATURE - LICENSEE 220070	DATE	SIGNATURE NRC IN	SPECTOR DATE