

Appendix A

Notice of Violation

Niagara Mohawk Power Corporation
Nine Mile Point, Unit 1

Docket No. 50-220
License No. DPR-63

As a result of the inspection conducted on May 18 - 21 and June 22 - 24, 1982, and in accordance with the NRC Enforcement Policy, 10 CFR 2, Appendix C (45 FR 9987, March 9, 1982), the following violation was identified:

Technical Specification 6.1? requires that procedures for personnel radiation protection be prepared and adhered to for all operations involving personnel radiation exposure. Radiation Protection Procedure RP-2, Revision 1, Radiation Work Permit Procedure, Section 5, requires the RWP leadman to ensure that all RWP instructions are followed. RWP No. 8415, General Clean-Up of East and West Instrument Rooms, dated May 18, 1982, required that rubber gloves, a cap, and taped coveralls be worn.

Contrary to the above, on May 18, 1982, a leadman, working under RWP No. 8415, did not ensure that all RWP instructions were followed. The leadman and his co-worker wore only shoecovers and cotton glove liners as protective clothing.

This is a Severity Level V violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Niagara Mohawk Power Corporation is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.