DMB

NRC FORM 591 PART 1 (7-91) 10 CFR 2.201

SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

				Page 1 of _/	
1. LICENSEE Harlow & Associates Loro & Roserve & Miscola, MT 59801		2. REGIONAL OFFICE REGION IV U S NUCLEAR REGULATORY COMMISSION 611 RYAN PLAZA DRIVE SUITE 400 ARLINGTON TX 76011-8064			
DOCKET NUMBER(S) 4. LICENSE NUMBER(I		3)	5. DATE OF INSPECTION		
-030-20327/94-01 25-23162-		01	2/8/94		
LICENSEE: The inspection was an examination of the acti Regulatory Commission (NRC) rules and regu procedures and representative records, intervi- follows:	lations and the condition	s of your license. The ins	pection consisted of selective e	xaminations of	
Within the scope of this inspection, in	no violations were observ	red.			
The inspector also verified the steps questions on those actions at this tire. During this inspection certain of you NOTICE OF VIOLATION, which is recommendated.	me. r activities, as described	below or attached, were in	n violation of NRC requirements		
	quired to be posted in ac	cordance with 10 CFR 19	31.		
L A			was not properly posted to		
	indicate the presence of a				
	B of sealed sources were not				
performed at the proper frequencies. 10 CFR or License Condition Number					
C. Records of	C. Records of were not properly maintained.				
10 CFR	10 CFR or License Condition Number				
D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.					
E. Reports or notification of					
10 CFR or License Condition Number					
or defise condition number					
				J\$-09	
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NRC.	described by me to the made in accordance wit	Inspector will be taken to th the requirements of 10	correct the violations identified CFR 2.201. No further response	in the items checked e will be submitted	
SICHATURE LICENSEE	DATE	SIGNATURE - NRC INS	SPECTOR	DATE	
9402240028 940208 PDR ADDCK 03020327 C PDR		Allet L Xu	and h	2/8/04	