

APPENDIX A

REVISED NOTICE OF VIOLATION

Tennessee Valley Authority
Browns Ferry

Docket No. 50-259
License No. DPR-33

As a result of the inspection conducted on March 23-26, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V, as implemented by TVA Topical Report TR-75-1, paragraph 17.2.5, requires activities affecting quality to be prescribed by documented instructions, procedures or drawings of the type appropriate to the circumstances.

Contrary to the above, Drawing No. 47W406-1, a documented drawing prescribed for installation of the local leak rate test line on the Unit 1 Reactor Water Cleanup system, was inappropriate to operational circumstances in that it did not specify support for a two-foot horizontal segment of the test line on which there were mounted two 13 lb. valves. On March 20, 1982, the vent line fractured due to detrimental loading that occurred because of the lack of a support.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office with thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JUN 16 1982