82-016/03L-0 LICENSEE EVENT REPORT

CAR 1393

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N Y R E G 1 2 0 0 - 0 0 0 0 0 0 3 4 1 1 1 1 1 1 6 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 2 4 4 7 0 7 2 2 8 2 8 0 8 2 1 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	While performing surveillance testing on the Containment Spray System at 100% power,
0 3	the discharge check valve on the "B" Containment Spray Pump (Valve 862B) failed to
0 4	seat at the required differential pressure. This required the pump to be declared
0 5	inoperable and is reportable by Technical Specification 6.9.2.b(2).
0 6	
0 7	
08	SYSTEM CAUSE CAUSE COMP. VALVE
0 9	S A 11 E 12 C 13 V A L V E X 14 SUBCODE SUBCOD
	1) LER/RO EVENT YEAR REPORT NO. 0 1 6 CODE TYPE CODE TYPE OCCURRENCE REPORT NO. 0 3 LL 0 32
	ACTION FUTURE COMPONENT NETHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER MANUFACTURER B 18 A 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 N 25 A 2 0 0 26
1 0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The Aloyco 6" self actuated swing check valve type 2376 has shown wear on the pin and p
1 1	swing arm. Due to design and material changes by the vendor, spare parts delivery
1 2	has been delayed. As parts are available, the valve will be reinspected and the
1 3	internals replaced during the next scheduled outage.
1 4	
1 5	STATUS POWER OTHER STATUS OTHER STATUS OF DISCOVERY DISCOVERY DESCRIPTION (32) B (31) Valve Exercise Periodic Test 80
1 6	ACTIVITY CONTENT RELEASED OF RELEASE NA AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA
1 7	PERSONNEL EXPOSURES O O O O Z Z O O O O O O O O O O O O O
7 8	9 PERSONNEL INJURIES O O O O O O O O O O O O O O O O O O O
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
7 8	Z 42 NA 9 10 8209030148 820821 NRC USE ONLY
2 0	ISSUED DESCRIPTION (45) PDR ADOCK 05000244 PDR
	T. B. Sabular 315-524-4446 Ext. 214