



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

February 14, 1994

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Outage Update

In December 1993 we completed a Unit 2 refueling outage. During the outage we completed a number of projects. Some of these projects fulfill actions about which we had corresponded with you. The following commitments have been completed, as noted.

<u>TASK ID</u>	<u>SUBJECT</u>	<u>STATUS</u>
M56155	Prairie Island 2 - NUREG 0737, Part I.D.1.2, Detailed Control Room Design Review Summary Report	Prairie Island Unit 2 Control Room Design Review commitments have now been completed.
M74299	Prairie Island 2 - Bulletin 89-02, Stress Corrosion Cracking of High Hardness Type 410 Stainless Steel Internal Preloaded Bolting in Anchor Darling Valves	All requirements of the bulletin have now been completed for Prairie Island Unit 2.

This letter provides the status of two projects but contains no new NRC commitments.

220037

ADD 1/0


9402280200 940214
PDR ADDCK 05000282
P PDR

USNRC

February 14, 1994

Page 2 of 2

Please contact Jack Leveille (612-388-1121, Ext. 4662) if you have any questions related to this letter.



Roger O Anderson

Director

Licensing and Management Issues

c: Regional Administrator - Region III, NRC
Senior Resident Inspector, NRC
NRR Project Manager, NRC
J E Silberg