

AUG 26 1982

University Hospitals of Cleveland  
ATTN: Bernard C. Rudegair  
Assistant Vice President  
2065 Adelbert Road  
Cleveland, Ohio 44106

License No. 34-05469-01  
03002745

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. Matson of this office on August 9 and 10, 1982, of activities authorized by NRC Byproduct Material License No. 34-05469-01 and to the discussion of our findings with you and Dr. P. J. Rao at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2


Enclosure: Appendix,  
Notice of Violation

cc w/encl:


P. J. Rao, Ph.D., Radiation  
Safety Officer

DMB/Document Control Desk (RIDS)

RIII

  
Matson,sv  
8/19/82

RIII

  
Sreniawski

8/26/82

IE HQ FILE COPY

8209030347 820826  
NMS LIC30  
34-05469-01 PDR

DMB IE-07