



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

August 23, 1982

Mr. Ronald C. Haynes
Director, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 82-005/01 P-0
ER 100450 FILE 841-23
PLA- 1244

Docket No. 50-387
License No. NPF-14

Dear Mr. Haynes:

This transmission confirms the telephone report of August 20, 1982 by F.T. Eisenhuth, to Mr. L. Tripp of your staff, regarding a failure of the Control Room Emergency Outside Air Supply System (CREOASS) to automatically start on an isolation signal.

This condition is considered reportable in accordance with Technical Specification 6.9.1.8.e.

H.W. Keiser
Superintendent of Plant-Susquehanna

DGM/cw

cc: Richard C. DeYoung - Director, Office of Inspection and Enforcement
Norman H. Haller - Director, Office of Management and Program Control
U.S.N.R.C. - Resident Inspector, Susquehanna SES

IE 29