

AUG 31 1982

Whitworth, Foust, Stearnes and  
Sebek, Inc.  
ATTN: Mr. John E. Hill  
412 Tanner, Post Office Box 548  
Sikeston, Missouri 63801

License No. 24-20197-01

Gentlemen:

This refers to the routine safety inspection conducted by Dr. L. W. Shatterly of this office on August 19, 1982, of activities authorized by NRC Byproduct Material License No. 24-20197-01 and to the discussion of our findings with you at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1

Enclosure: Appendix,  
Notice of Violation

cc w/encl:  
DMB/Document Control Desk (RIDS)

RIII

RIII

Shatterly/sv  
8/30/82

Wiedeman  
9/1/82

8209080055 820901  
NMS LIC30  
24-20197-01 PDR

IE HQ FILE COPY

DMB:ZE07