

Appendix

NOTICE OF VIOLATION

Whitworth, Foust, Stearnes
and Sebek, Inc.

License No. 24-20197-01

As a result of the inspection conducted on August 19, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 14A requires that you test your sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months.


Contrary to the above, the NRC inspector learned through statements by licensee representatives and a review of records this requirement was not met. Specifically, your Campbell Pacific corporation moisture-density gauge was leak tested May 20, 1981, and August 11, 1982. This is a period in excess of the required six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

9-1-82

Dated



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1