



August 16, 1982

U.S. Nuclear Regulatory Commission
 Attn: Thomas T. Martin, Director
 Division of Engineering and Technical Programs
 Region I
 631 Park Avenue
 King of Prussia, Pennsylvania 19406

P.O. BOX 25141
 ALBUQUERQUE, NEW MEXICO 87125

Docket No. 30-18920

Inspection No. 82-01

Gentlemen:

This is in response to your letter dated July 23, 1982 concerning inspection 82-01 of NRC License No. 37-19586-01MD. As noted by your inspector, hood air flow was erroneously checked annually instead of at the required semi-annual frequency. In addition, this omission was not detected during our periodic audits. Both our routine check list and our audit checklist have been corrected to assure semi-annual checks, the next being due by November, 1982. Since a check was made on May 24, 1982, the Harrisburg pharmacy is now in full compliance.

Should you have any further questions concerning this reply, please contact me.

Sincerely,

NUCLEAR PHARMACY, INC.

Carl M. DeJuliis

Carl M. DeJuliis, R.Ph.
 Pharmacy Manager

cc: Central File
 Reading File
 License Files
 R. McClintock
 S. Dessel
 A. Solomon

8209080545 820901
 NMS LIC30
 37-19586-01MD PDR