



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

NORRIS L. STAMPLEY
SENIOR VICE PRESIDENT

September 2, 1982

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Insufficient ECCS Operability
Reference: LER 82-039/03 L-0
AECM-82/379

On August 4, 1982, it was noted that during initial core loading, a surveillance test, required because less than the required number of ECCS systems were operable, was not performed at the required frequency. Attached is LER 82-039/03 L-0 with supplementary information.

Yours truly,

NLS:ac
Attachment

cc: Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8209080629 820902
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

LE 22

82 SEP 3 AIO: 40
REGIONAL
ATLANTA, GEORGIA