NIAGARA MOHAWK POWER CORPORATION

NIAGARA A MOHAWK

300 ERIE BOULEVARD, WEST SYRACUSE, N. Y. 13202

August 9, 1982

Mr. Thomas T. Martin, Director Division of Engineering and Technical Programs United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, PA 19406

> Re: Docket No. 50-220 Inspection Report No. 82-09

Dear Mr. Martin

This refers to the routine safety inspection conducted by Messrs. S. Richards and R. Paolino of your office on June 15 through 18, 1982, at Nine Mile Point Unit #1, Scriba, New York, of activities authorized by NRC License No. DPR-63 and to the discussions of your findings held by Mr. S. Richards of your office with Mr. T. Roman of our staff at the conclusion of the inspection and to subsequent telephone discussions between D. Beckman of your office and T. Perkins and T. Roman of our staff on June 25, 1982, and June 28, 1982.

ITEM A.

10 CFR 50, Appendix B, criterion V, requires activities affecting quality to be prescribed by and accomplished in accordance with documented instructions or procedures of a type appropriate to the circumstances. The licensee's Fire Protection Quality Assurance Program, dated June 25, 1979, Section 3.3, requires inspections tests, administrative controls, fire drills, and training required by the Fire Protection System be accomplished in accordance with current approved instructions or procedures. Fire Prevention Procedure No. NI-FP-2, "Welding and Cutting", requires a fire watch be stationed during welding and cutting operations.

Contrary to the above, on June 17, 1982, Fire Protection activities were not conducted in accordance with approved procedures in that welding was observed in the Screen and Pump House without a fire watch present.

8209080630 820901 PDR ADOCK 05000220 PDR being followed.

3. Due to these actions, Niagara Mohawk Power Corporation is presently in full compliance.

Very truly yours,

Vice President

Nuclear Generation

TEL/HB/jm