

Georgia Power Company
333 Piedmont Avenue
Atlanta, Georgia 30308
Telephone 404 526-7020

Mailing Address:
Post Office Box 4545
Atlanta, Georgia 30302

J. T. Beckham, Jr.
Vice-President and General Manager
Nuclear Generation



August 30, 1982

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

NRC DOCKETS 50-321, 50-366
OPERATING LICENSES DPR-57, NPF-5
EDWIN I. HATCH NUCLEAR PLANT UNITS 1, 2
INSERVICE INSPECTION OF ASME CATEGORY B-H
WELDED SUPPORTS-RELIEF REQUEST

Gentlemen:

In accordance with the requirements of the 1974 Edition of ASME Section XI, Category B-H welded supports require a volumetric examination. These particular supports on Hatch Units 1 and 2 have historically been difficult to examine volumetrically (UT) due to geometrical configuration.

The 1980 Edition of ASME Section XI with Addenda through Winter 1980 which has been approved by NRC requires only a surface examination for these supports.


The upcoming Unit 1 refueling outage originally scheduled for April 1982 is the last major outage which is to be covered by the 1974 Edition of the Code. As a result of the core reconstitution outage discussed in our letter dated October 7, 1981, the Unit 1 refueling outage will not begin until October 1982. A mandatory update to the 1980 Edition of Section XI is required by January 5, 1983 for both units. Unit 1 would have normally updated by August 30, 1982. However, we requested by letter dated November 10, 1981 an extension of the current inservice examination period to allow completion of all remaining second forty-month period examinations during the refueling outage now scheduled for October 1982. Unit 1 will update its program for the third forty-month period of commercial operation on January 5, 1983 which coincides with the program update for Unit 2. After that date, a surface examination will be the only examination required for Units 1 and 2 B-H supports.

Surface examination methods provide a high degree of reliability in detecting flaws in welded supports. Since a surface examination of B-H supports will be required in the future, Georgia Power Company plans to perform surface examinations in lieu of volumetric examinations for those category B-H supports scheduled for examination during the upcoming outages.

Your concurrence with this course of action is requested. Due to the impending need to make the necessary arrangements for performing the examinations during the upcoming outage, please advise us if you have any objections to the course of action discussed herein.

A047


8209090092 820830
PDR ADOCK 05000321
Q PDR

Georgia Power 

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
August 30, 1982
Page Two

If you have any questions in this regard, please contact this office.

Very truly yours,


J. T. Beckham, Jr.

JAE
JAE/blm

xc: H. C. Nix, Jr.
R. F. Rogers, III
J. P. O'Reilly