

P.O. Box 1866 • Bellevue, Washington 98009 • (206) 827-0711

August 24, 1982 QAS-82-044



U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Attention: Mr. Uldis Potapovs, Chief Vendor Program Branch

Gentlemen:

1 1 1

Mr. W. McNeill's report (No. 99900776/82-01) identifies a situation which this company felt to be a reportable condition as described by 10 CFR Part 21. This condition, although reported and documented internally and to the Commission office, was not written on the standard CNSI Nonconformance Report form as specified by CNSI Procedure CN-AD-015.

The following measures are, and have been, taken to preclude any recurrence of this situation:

- The procedure for nonconforming items (CN-AD-015) is being revised to more adequately reflect circumstances which may require 10 CFR Part 21 reporting. Completion of procedure revision will be accomplished by October 1, 1982.
- (2) CNSI personnel have received further indoctrination with regard to the Quality Program (QA-AD-001) and implementing procedures, in particular procedures for nonconforming equipment and component reporting.

Any future conditions adverse to quality which are nonconforming will be reported on the CNSI Nonconformance Report form and processed accordingly.

Sincerely,

CHEM-NUCLEAR SYSTEMS, INC.

uno /d

Bruno Svinis, Deputy Director Quality Assurance

BS:sj

8209090102 820907 PDR 0A999 EMVCNSI 99900776 PDR