

AUG 24 1982

APPENDIX A

NOTICE OF VIOLATION

Westinghouse Electric Corporation
Lester, Pennsylvania 19113

Docket No. 030-06109
License No. 37-03632-01

As a result of the inspection conducted on July 15, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified.

- A. 10 CFR 34.43(b) requires that a physical radiation survey be made after each radiographic exposure to determine that the sealed source has been returned to its shielded position. The entire circumference of the radiographic exposure device must be surveyed and, if the device has a source guide tube, the survey must include the entire length of the guide tube.

Contrary to the above, on July 15, 1982, a radiographer failed to perform a survey that was adequate to determine that the sealed source had returned to its shielded position. A survey which was intended to meet this requirement was performed, but was inadequate in that it did not include the entire circumference of the exposure device.

This is a Severity Level IV violation (Supplement IV).

- B. 10 CFR 34.44 requires that, whenever a radiographer's assistant uses radiographic exposure devices, he must be under the personal supervision of a radiographer. Personal supervision must include the radiographer watching the assistant's performance.

Contrary to the above, as of July 15, 1982, a radiographer's assistant occasionally performed radiography when not under the personal supervision of a radiographer. Although radiographers are present on the work site, they did not always enter the exposure facility with him and watch his performance.

This is a Severity Level IV violation (Supplement IV).

- C. Condition 16 of License No. 37-03632-01 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in your application dated January 6, 1982.

1. The first paragraph of Attachment 10 to Item 6(f) of this application requires that new employees be qualified as radiographers prior to being hired, since the training program is designed for radiographers only.

AUG 24 1982

Contrary to the above, a person hired with no previous training in radiography has been working as a radiographer's assistant since April 7, 1982.

This is a Severity Level IV violation (Supplement IV).

2. The last paragraph of Attachment 6 to Item 6(c) requires that pocket dosimeters be checked for accuracy at least yearly.

Contrary to the above, as of July 15, 1982, the pocket dosimeters had not been checked for accuracy since January 26, 1981, a period of more than a year.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Westinghouse Electric Corporation is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.