

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: MIDCC2, LICENSE NUMBER: 00000000000000000000, LICENSE TYPE: 41111, CAT 58

REPORT SOURCE: L, DOCKET NUMBER: 05000316, EVENT DATE: 081682, REPORT DATE: 090182

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 DURING COLD SHUTDOWN, AN OPERATOR DISCOVERED FIRE DOOR #374 UNABLE TO LATCH. THIS
03 CONDITION CONSTITUTED AN INOPERABLE PENETRATION FIRE BARRIER, CONTRARY TO T.S.
04 3.7.10. ACTION REQUIREMENTS WERE MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
05 PREVIOUS OCCURRENCES: 82-043, 82-045, 82-040. DOCKET 05/315: 82-031, 82-033,
06 82-038, 82-040.

SYSTEM CODE: AB, CAUSE CODE: X, CAUSE SUBCODE: Z, COMPONENT CODE: XXXXX, COMP SUBCODE: Z, VALVE SUBCODE: Z
LER NO REPORT NUMBER: 82, SEQUENTIAL REPORT NO.: 069, OCCURRENCE CODE: 03, REPORT TYPE: L, REVISION NO.: 0
ACTION TAKEN: BG, EFFECT ON PLANT: Z, SHUTDOWN METHOD: Z, HOURS: 0000, ATTACHMENT SUBMITTED: N, NPRO-4 FORM SUB.: N, PRIME COMP SUPPLIER: A, COMPONENT MANUFACTURER: Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 THE FAILURE WAS DUE TO LOOSE AND MISSING SCREWS. SCREWS WERE REPLACED/TIGHTENED AND
11 STAKED. INSPECTION PROCEDURE CHANGED TO REQUIRE STAKING OF ALL SCREWS IN DOORS AND
12 ASSOCIATED HARDWARE.

FACILITY STATUS: G, % POWER: 000, OTHER STATUS: NA, METHOD OF DISCOVERY: B, DISCOVERY DESCRIPTION: OPERATOR OBSERVATION

ACTIVITY CONTENT: Z, AMOUNT OF ACTIVITY: NA, LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES: 000, DESCRIPTION: NA

PERSONNEL INJURIES: 000, DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY: Z, DESCRIPTION: NA

PUBLICITY: N, NRC USE ONLY: 82090158 820901 PDR ADOCK 05000316 S PDR

NAME OF PREPARER: R. H. PIEHL, PHONE: 616-465-5901