

APPENDIX A
NOTICE OF VIOLATION

Northeast Nuclear Energy Company
Millstone Nuclear Power Station
Units 1, 2 and 3

Docket Nos. 50-245
50-336
50-423
License Nos. DPR-21
DPR-65
NPF-49

During an NRC inspection conducted on January 31 - February 4, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

10 CFR Part 73.71(d) states in part: (1) While in use, matter containing Safeguards Information shall be under the control of an authorized individual; and (2) While unattended, Safeguards Information shall be stored in a locked security container.

Contrary to the above, on January 28, 1994, a revision to the Millstone Security Plan, containing Safeguards Information, was determined not to have been in use or under the control of an authorized individual for an undetermined period of time, nor was it stored in a locked security container.

This is a Severity Level IV violation (Supplement III).

Pursuant to the provisions of 10 CFR 2.201, Northeast Nuclear Energy Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY G:MILL0706.CIR February 16, 1994

9403080031 940218
PDR ADDCK 05000245
G PDR

Any Safeguards Information, as defined in 10 CFR 73.21, contained in your submittal should be included in an enclosure so that the transmittal letter without the Safeguards Information can be placed in the NRC's Public Document Room in accordance with 10 CFR 2.790(a).

Dated at King of Prussia, Pennsylvania
this 17th day of February, 1994