## Docket No. 99900271/82-01

AUG 2 3 1982

Rosemount, Inc. ATTN: Mr. F. J. Oakley Vice President, Operations 12001 W. 78th Street Eden Prairie, MN 55344

Gentlemen:

This refers to the inspection conducted by Mr. L. B. Parker of this office on June 7-11, 1982, of your facility at Eden Prairie, Minnesota, associated with the manufacture of temperature and pressure instrumentation and to the discussions of our findings with you and members of your staff at the conclusion of the inspection.

This inspection was made in response to: (1) requests by Region II of the Nuclear Regulatory Commission (NRC) to evaluate: (a) a 10 CFR 50.55(e) report by Mississippi Power and Light Company (MP&L) concerning corroded terminal boards on transmitters used at Grand Gulf Nuclear Station (GGNS); (b) a 10 CFR 50.55(e) report by MP&L concerning "0" ring seals on transmitters which do not provide a seal that conforms with the requirements of NUREG-0588 for Class 1E equipment located inside containment; (2) a report from the NRC Senior Resident Inspector at Millstone Nuclear Station Units 1 and 2 and a 10 CFR 50.55(e) report to the NRC Region IV from Waterford SES Unit No. 3 concerning corrosion degradation of resistance temperature detector (RTD) leads at the terminal block connection in the head of the assembly; and (3) a 10 CFR 50.55(e) report by Pennsylvania Power and Light Company (PP&L) concerning a potential diode failure (identified by Rosemount) on the amplifier board of pressure transmitter Models 1151 and 1152 with output codes A and D at Susquehanna Steam Electric Station.

Areas examined and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection it was found that the implementation of your QA program failed to meet certain NRC requirements. The specific findings and references to the pertinent requirements are identified in the enclosures to this letter.

Please provide us within 30 days from the date of this letter a written statement containing: (1) a description of steps that have been or will be taken to correct these items; (2) a description of steps that have been or will be taken to prevent recurrence; and (3) the date your corrective actions and preventive measures were or will be completed. Consideration may be given to extending your response time for good cause shown. B209090267 B20823

	0.511				PDR GA999 EMVRC	DSM
OFFICE	CI : R&CPS &	SC:R&CPS	BC: VPBTB	D: IES 900	99900271 RA:BIV	PDR
SURNAME	LBParker/jr	IBarnes	UPotapovs	EHJohnson	Jicollins	1
DATE	8/13/82	8//3/82	8//3/82	8/19/82	8/13/82	······································
NRC FORM 318 (10-80) NRCM 0240			OFFICIAL RECORD COPY			

Rosemount, Inc.

.

1 × 14

The response requested by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be exempt from disclosure under 10 CFR 9.5(a)(4), it is necessary that you (a) notify this office by telephone within 10 days from the date of this letter of your intention to file a request for withholding; and (b) submit within 25 days from the date of this letter a written application to this office to withhold such information. If your receipt of this letter has been delayed such that less than 7 days are available for your review, please notify this office promptly so that a new due date may be established. Consistent with Section 2.790(b)(1), any such application must be accompanied by an affidavit executed by the owner of the information which identifies the document or part sought to be withheld, and which contains a full statement of the reasons on the basis which it is claimed that the information should be withheld from public disclosure. This section further requires the statement to address with specificity the considerations listed in 10 CFR 2.790(b)(4). The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified periods noted above, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Uldis Potapovs, Chief Vendor Program Branch

Enclosures:
1. Appendix A - Notice of Nonconformance
2. Appendix B - Inspection Report No. 99900271/82-01
3. Appendix C - Inspection Data Sheets (4 Pages)
bcc:

IE Files AEOD QAB NRC:PDR Reg. Administrators, I, II, III, IV, V EHJohnson, RIV

NRC FORM	318 (10-80) NRCM	0240	OFFICIAL	RECORD	COPY		
		·····	**************	****************	a managementer	*************	aanaanaanaanaanaa iy
DATE		1 (H (1971) 201	물건물 두 달랐다		비행이 지난 영상		
SURNAME						and an	******************
1.1	* *************		*****************			****************	
OFFICE					물건 가슴 물 물건이 있어?		