PMB



## Independent Testing Laboratories

Post Office Box 219257, Houston, Texas 77218-9257, (713) 579-0561

February 8, 1994

U.S. Nuclear Regulatory Commission Regional IV Administrator 611 Ryan Plaza Drive #400 Arlington, TX 76011



Gentlemen:

Subject:

Reply to a Notice of Violation

In reference to your inspection report 150-00042/93-01 regarding the inspection conducted by Mr. Robert A. Brown on December 14, 1993, in Watertown, South Dakota, it was found that our personnel did not have proper shipping papers for the Iridium 192 source which was being used at this jobsite. It was our understanding that our daily survey log contained sufficient information to comply with the appropriate Department of Transportation (DOT) regulation.

Since your January 3, 1994, telephone conversation with Mr. Homer Wilson, VP of Operations for our company, a form was prepared. We have enclosed this form for your review.

This form has been distributed to all personnel of Independent Testing Laboratories (ITL) on or before January 17, 1994. Therefore, based on this telephone conversation, we feel this form will bring ITL into full compliance with all appropriate regulations.

If you have any questions or need additional information, please don't hesitate to contact us at 1-800-643-8136.

Sincerely yours,

Walter C. Crager

Radiation Safety Officer

cjb/57ADM1

25002G

CC:

J. W. Lawson, Sr.

U.S. Nuclear Regulatory Commission

94-0508


ú

IE-07

A DIVERSIFIED INSPECTIONS COMPANY

FACSIMILE: (713) 579-6464

9403080382 940208 PDR STPRG ESGTX (800) 643-8136



## BILL OF LADING RADIOACTIVE MATERIAL

1 Model 650 Snipping Container	
Radioactive Material, special form NOS UN2974	
Iridium 192, ci, GBq Total* Radioactive Yellow Transportation Index USA/6717/B(U) type B	
Emergency Response No. (713) 427-1138.	
Radiographer(s)	
Date	
Radiation Safety Officer	
Date	

\* GBq = no. of curies x .037

1ADM1266

A DIVERSIFIED INSPECTIONS COMPANY

FACSIMILE: (713) 579-6464