



DEPARTMENT OF THE AIR FORCE
HEADQUARTERS UNITED STATES AIR FORCE
BOLLING AFB DC 20332

PDR

40-8807


Return to 396-55

REPLY TO AFMSC/ SGPZ
ATTN OF BROOKS AFB TEXAS 78235

19 AUG 1982

SUBJECT Notification of Change (USNRC License STB-1407)

TO Radioisotope Licensing Branch
Division of Fuel Cycle and Material Safety
U.S. Nuclear Regulatory Commission
Washington DC 20555



1. This is to advise you of a change in the planned location for repair/rework of magnesium-thorium components authorized by license number STB-1407 issued February 22, 1982 to the Directorate of Maintenance, Tinker Air Force Base, Oklahoma.
2. The gear box repair/rework was to have originally been conducted within an enclosure constructed in area T-67-W-67 of building 3001. Subsequent plant layout modifications now require this enclosure to be located in area X-67-Y-67 within the same building. This relocation is illustrated on the attached diagram. Since no work has yet been started, this simple relocation does not change any radiological health considerations of this license, nor any other representations made in the original application dated October 13, 1981.
3. Please refer any subsequent correspondence on this subject to this office.

VICTOR C. FURTADO, Colonel, USAF, BSC
Chairman, USAF Radioisotope Committee
Office of the Surgeon General


1 Atch
Sketch of Location Change
in Building 3001



FEE EXEMPT


APPENDIX C

GEARBOX SHOPS J.79




APPENDIX C

GEARBOX SHOPS J.79




APPENDIX C

GEARBOX SHOPS J.79



APPENDIX C

GEARBOX SHOPS J.79



APPENDIX C

GEARBOX SHOPS J79

