SAFETY INSPECTION

KVIL

L. LICENSEE

R.B.S., Inc. P. O. Beawer S White Sulphur Springs, WVA 24986 2. REGIONAL OFFICE

U. S. Nuclear Regulatory Commission Region II, Suite 3100 101 Marietta St., N. W. Atlanta, Ga. 30303

3. DOCKET NUMBER(S)

30-19562

4. LICENSE NUMBER(S)

47-19937-01

5. DATE OF INSPECTION

Licensee

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
 THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

C. of sealed sources were not performed at the proper frequencies. 10 CFR License Condition Number

E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

H.

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by

8209160318 820812 NMS LIC30 47-19937-01 PDR

SIGNATURE - LICENSEE

DAT

SIGNATURE - NRC INSPECTOR

8/12/82

1