



DEPARTMENT OF THE ARMY
HEADQUARTERS UNITED STATES ARMY MISSILE COMMAND
REDSTONE ARSENAL, ALABAMA ~~35899~~ 35898

2 / 30 AID : 02

24 August 1982

DRSMI-XO

SUBJECT: Report Numbers 01-00126-16/82-01 and 01-00126-17/82-01

Mr. A.F. Gibson
Chief, Technical Inspection Branch
Division of Engineering and Technical Programs
US Nuclear Regulatory Commission, Region II
101 Marietta Street, N.W.
Atlanta, Georgia 30303

Dear Sir:

This command acknowledges the violations referenced in paragraphs A and B, appendix A of subject reports (Incl).

Violations occurred due to work slippage resulting from restructuring of the command radiation protection program. These changes required revision of the local regulation for ionizing radiation protection and changing the membership of our Radiation Control Committee.

Leak tests have been performed on each sealed source containing licensed material under License Condition 14-A of License No. 01-00126-17. Leak test dates have been entered on a calendar of recurring program elements to prevent future slippages.

The Ionizing Radiation Control Committee (IRCC) convened on 5 August 1982, in accordance with License Condition 16 of License No. 01-00126-16. The IRCC will be convened at least once per quarter. Projected meeting dates have also been entered on the calendar of recurring program elements.

Implementation of the required program elements as stated in the above paragraphs has resulted in full compliance as of this date.

8209160349 820902
NMS LIC30
01-00126-16 PDR


DRSMI-XO

24 August 1982

SUBJECT: Report Numbers 01-00126-16/82-01 and 01-00126-17/82-01

For additional information concerning this response, contact Mr. Fred Feld,
commercial telephone number (205) 876-3404/8136 or autovon /46-3404/8136.

Sincerely,



FRANCIS E. HART
Chief
Safety Office

1 Incl
As stated

Copies Furnished:
DRCSF-P, Mr. Darwin Taras
DRXTM-SR, Mr. Del Loney
DRSMI-KLU, Mr. Jim Reid