

APPENDIX A
NOTICE OF VIOLATION

U.S. Army Missile Command
Redstone Arsenal

License Nos. 01-00126-16 &
01-00126-17

As a result of the inspection conducted on June 29, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified.

- A. License Condition 14.A of License No. 01-00126-17 requires that each sealed source containing licensed material shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the Perkin Elmer Nickel-63 sealed source previously leak tested on November 13, 1981, was not leak tested in May 1982 as required.

This is a Severity Level V Violation (Supplement VI).

- B. License Condition 16 of License No. 01-00126-16 requires material be used in accordance with statements, representations, and procedures contained in your application dated December 14, 1976. One procedure requires that your Radiation Control Committee meet on a quarterly basis.

Contrary to the above, the Radiation Control Committee has not met quarterly since May 1981.

This is a Severity Level V Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: July 16, 1982