

LICENSEE EVENT REPORT

Attachment to AECM-82/402

Page 1 of 1

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 57 CAT 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T
 01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 8 | 1 | 2 | 8 | 2 | 8 | 0 | 9 | 1 | 3 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 02 | While performing work to reroute cables for divisional separation technicians noted
 03 | a fire barrier between two control room cabinets (P712E and P712B) which was not
 04 | sealed. A Limiting Condition for Operation was initiated pursuant to T.S.3.7.7 and
 05 | the action statement entered. Operations personnel started an hourly fire watch in
 06 | the Control Room area involved.

09 | A | B | 11 | B | 12 | C | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16
7 8 9 10 11 12 13 18 19 20
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 | 8 | 2 | 21 | 22 | 0 | 4 | 8 | 24 | 26 | / | 0 | 3 | 28 | 29 | L | 30 | - | 31 | 0 | 32
21 22 23 24 26 27 28 29 30 31 32
 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 18 | Z | 18 | B | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | A | 25 | Z | 9 | 9 | 9 | 26
33 34 35 36 37 40 41 42 43 44 47
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 10 | The unsealed fire barrier was due to construction oversight. The maintenance work
 11 | order for cable reroute will close the fire barrier. A follow up report will be
 12 | submitted within the next 60 days.
 13 |
 14 |

15 | B | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Construction Activity | 32
7 8 9 10 12 13 44 45 46 80
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45 80
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 17 | 0 | 0 | 0 | 37 | 38 | NA | 39
7 8 9 11 12 13 80
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12 80
 PERSONNEL INJURIES NUMBER DESCRIPTION
 19 | Z | 42 | NA | 43
7 8 9 10 80
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 20 | N | 44 | NA | 45
7 8 9 10 80
 PUBLICITY ISSUED DESCRIPTION
 8209200059 820913
 PDR ADOCK 05000416
 S PDR
 NRC USE ONLY
68 69 80

NAME OF PREPARER Original Signed by Arthur J. White

PHONE: _____

SPO 017-926