



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

September 10, 1982


Mr. James G. Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/82-25 for Zion Generating Station. This event was originally classified as a 30 day reportable event. However, as the result of an internal review, it was reclassified to a 14 day reportable event on September 1, 1982. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 9/1/82 and by telegram/mailgram on 9/2/82.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.2, which states that operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the technical specifications require a 14 day written report.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/82-25

8209200063 820910
PDR ADOCK 05000295
S PDR

SEP 13 1982

IE 22