

The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2.790.

U.S. NUCLEAR REGULATORY COMMISSION

Region V

Report No. 70-1257/82-08 (IE-V-519)

Docket No. 70-1257 License No. SNM-1227 Safeguards Group 1

Licensee: Exxon Nuclear Company

2101 Horn Rapids Road

Richland, Washington 99352

Facility Name: \_\_\_\_\_

Inspection at: Richland, Washington

Inspection Conducted: August 12, 1982

Date of Last Material Control and Accounting Inspection Visit: April 14-21, 1982

Type of Inspection: Special US/IAEA Safeguards

Inspectors: A. V. Wieder 9/15/82  
A. V. Wieder, Auditor Date Signed

\_\_\_\_\_  
Date Signed

\_\_\_\_\_  
Date Signed

Approved by: L. R. Norderhaug 9/15/82  
L. R. Norderhaug, Chief, Safeguards Branch Date Signed

Inspection Summary:

Areas Inspected: Routine unannounced inspection observing IAEA inspectors perform selected inventory verification measurements of UF<sub>6</sub> cylinders and fuel rod loading. This inspection involved 8 onsite inspector-hours by one NRC inspector during regular hours.

Results: No items of noncompliance were noted.