

APPENDIX A
NOTICE OF VIOLATION

Philadelphia Electric Company
Peach Bottom Unit 2

Docket No. 50-277
License No. DPR-44

Based on the results of the inspection conducted on August 16-20, 1982, and in accordance with NRC Enforcement Policy 47 FR 9987, March 9, 1982, the following violation was identified:

Technical Specification 6.9.2.a(3) requires prompt notification within 24 hours with written follow-up within 10 working days for any abnormal degradation discovered in primary containment.

Contrary to the above, as of August 20, 1982, no notification was given for the abnormal degradation in primary containment, as evidenced by unacceptable Local Leak Rate Test results for nine containment isolation valves, discovered on various occasions during the Unit 2 refueling outage from February 20, 1982, to June 25, 1982.

This is a Severity Level IV violation (Supplement I) applicable to DPR-44.

After the violation was identified by the inspector, Licensee Event Report 82-021/03L-0 on the above subject was submitted with a letter dated August 25, 1982.

Pursuant to the provisions of 10 CFR 2.201, Philadelphia Electric Company is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply including: (1) additional corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

OFFICIAL RECORD COPY

8210070322 820922
PDR ADOCK 05000277
G PDR