

APPENDIX A

NOTICE OF VIOLATION

Niagara Mohawk Power Corporation
Nine Mile Point, Unit 1

Docket No. 50-220
License No. DPR-63

As a result of the inspection conducted August 1-31, 1982, and in accordance with the NRC Enforcement policy, (10 CFR 2, Appendix C) published in the Federal Register Notice (47 FR 9987) dated March 9, 1982, the following violation was identified:

- A. Technical Specification 6.11 states: "Procedures for personnel radiation protection shall be prepared consistent with the requirements of 10 CFR Part 20 and shall be approved, maintained, and adhered to for all operations involving personnel radiation exposure."

Radiation Protection Procedure RP-2, "Radiation Work Permit Procedure," Revision 1, dated February 13, 1979 requires in Section 5.6, that if a qualitative fit test is specified on the RWP, indication of having passed the test must be indicated by a "✓" in the "Passed Fit Test" column when signing in.

RWP #1166 dated August 26, 1982 for work inside the drywell and on Reactor Building elevation 237', required a fit test for those individuals wearing full face respirators.

Contrary to the above, on August 26, 1982, ten individuals required to wear full face respirators had not indicated that a qualitative fit test had been performed.

This is a Severity Level V Violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Niagara Mohawk Power Corporation is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations, and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.

OFFICIAL RECORD COPY