

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M A Y K R 1 000 - 00000000 - 000 3411111 4 \_\_\_\_\_ 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 050000029 7090282 8100182 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 During normal operation in Mode 1, the auxiliary boiler room sprinkler s  
03 ystem was isolated to stop and repair a gasket leak. The system is requi  
04 red to be operable by T.S. 3.7.10.2.d. This is the first failure of this  
05 nature. There is no redundant sprinkler system in the room but other fi  
06 re suppression equipment is available for use in the area. During the tw  
07 o hour outage a continuous fire watch with suppression equipment was sta  
08 tioned. There was no adverse effect to the public health and safety. 80

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
A B 11 E 12 B 13 V A L V E X 14 C 15 A 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 2 0 2 7 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 R 1 6 3 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 The cause of this occurrence was a gasket leak between the upper flange  
11 and body of valve FS-V-739. The valve is a 3 inch, carbon steel, Model C  
12 , wafer check valve manufactured by the Reliable Automatic Sprinkler Co.  
13 , Inc. The leak was caused by insufficient gasket contact with the valve  
14 . The gasket was replaced in kind. No further actions are necessary. 80

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
E 28 0 8 2 29 N/A A 31 Operator Observation  
7 8 9 10 12 13 44 45 46 80  
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
Z 33 Z 34 N/A N/A  
7 8 9 10 11 44 45 80  
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
0 0 0 37 Z 38 N/A  
7 8 9 11 12 13 80  
18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
0 0 0 40 N/A  
7 8 9 11 12 80  
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
Z 42 N/A  
7 8 9 10 80  
20 PUBLICITY ISSUED DESCRIPTION (45)  
N 44  
7 8 9 10 80

8210130225 821001  
PDR ADOCK 05000024  
S PDR

NRC USE ONLY

NAME OF PREPARER: Edwin L. May PHONE: (413) 625-6140