



MAR 01 1982



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

BC.

LER # 282-81011

EVENT DATE 810812

NSAC REC'D. 810831

INPO REC'D. _____

August 24, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Inoperability of D2 Diesel Generator While D1 was OOS for PM

The Licensee's Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.b since the units were operated for a few minutes less conservatively than the least conservative aspect of the limiting condition for operation established in the technical specification.

Thomas Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

*1E22
BACKFIT
ADD:
M COLLINS
CE*

8210150381 810824
PDR ADOCK 05000282
S PDR