


CENTRAL MISSOURI PROFESSIONAL SERVICES, INC.

2500 EAST McCARTY • JEFFERSON CITY, MISSOURI 65101 • (314) 634-3455

DCD/DCB



Engineering • Surveying

Fax: (314) 634-8898

August 2, 1990

Mr. Roy J. Caniano, Chief
UNITED STATES NUCLEAR REGULATORY
COMMISSION
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Re: License No. 24-20300-01
Docket No. 030-18218
Safety Inspection

Dear Mr. Caniano:

In reference to your July 26, 1990 letter and Notice of Violations, please find listed below our written statement and explanation:

- 1) The correction was already taken. Our current NRC pamphlet stated leak tests were not required when the instrument was not in use or in storage. We weren't aware our license required us to make six month leak tests no matter what the circumstances.
- 2) We have marked our suspense calendar and six month tests will be made under all circumstance in the future.
- 3) Corrective action had already been taken and we are in full compliance.

Should you have any questions or require additional information, please advise.

Sincerely,

CENTRAL MISSOURI PROFESSIONAL
SERVICES, INC.

A handwritten signature in cursive script, appearing to read "Louis H. Vetter".

Louis H. Vetter, P.E.

LHV/mjc
cc: Jack Schuler

9008270083 900802
REG3 LIC30
24-20300-01 PDC

AUG 6 1990

110
IE07